



GEOMETRÍA DE PLAQUITAS

45





P	M	K	N	S	H
Consultar diagrama					
WCMT 06, WCMX 06					

46




P	M	K	N	S	H
Consultar diagrama					
WCMT 04, WCMX 03, WCMX 04					

47



P	M	K	N	S	H
Consultar diagrama					
WCMT 05, WCMX 05					

48




P	M	K	N	S	H
Consultar diagrama					
WCMT 08, WCMX 08					

GEOMETRÍA DE PLAQUITAS

UM






P	M	K	N	S	H
■	■	■	■	■	■


Consultar diagrama

WCMT 04, WCMT 05

SCET - UD



	a
SCET 050204-UD	0,12
SCET 060204-UD	0,15
SCET 070308-UD	0,15
SCET 09T308-UD	0,15
SCET 120408-UD	0,20
SCET 150512-UD	0,20




P	M	K	N	S	H
■	■	■	■	■	■


Consultar diagrama

SCET - UD

XPET AP



	a
XPET 0502AP	0,10
XPET 0602AP	0,10
XPET 0703AP	0,15
XPET 0903AP	0,25
XPET 11T3AP	0,25
XPET 12T3AP	0,25
XPET 1504AP	0,25
XPET 1904AP	0,25




P	M	K	N	S	H
■	■	■	■	■	■

Consultar diagrama


XPET AP

GEOMETRÍA DE PLAQUITAS

SCET - SD




SCET 050204-SD	0,04
SCET 060204-SD	0,06
SCET 070308-SD	0,08
SCET 09T308-SD	0,10
SCET 120408-SD	0,10
SCET 150512-SD	0,10




P	M	K	N	S	H
Consultar diagrama					
SCET - SD					

XPETAP- SD



XPET 0502AP-SD	0,04
XPET 0602AP-SD	0,05
XPET 0703AP-SD	0,08
XPET 0903AP-SD	0,10
XPET 11T3AP-SD	0,10
XPET 12T3AP-SD	0,10
XPET 1504AP-SD	0,10
XPET 1904AP-SD	0,12



P	M	K	N	S	H
Consultar diagrama					
XPETAP - SD					